

OFFICE OF SUB DIVI. ENGINEER, CONST. SUB DIVISION PWD (B&R),  
SRI ANANDPUR SAHIB.

Email ID: [pwdaps@gmail.com](mailto:pwdaps@gmail.com)

No = 121

Date:- 29.02.24

**BUILDING SAFETY CERTIFICATE**

It is certified that the existing buildings of Sri Dashmesh Academy, Anandpur Sahib Distt. Rupnagar (Punjab) is having blocks/Floors as per the details given below:-

Details of Block(s) in school	Block (1) Admin. Block	Block (2) Class Rooms Block A	Block (3) Class Rooms Block B	Block (4) Class Rooms Block C
No. of Floor(s) in the Block	Two floors	Two floors	Two floors	Two floors


Details of Blocks(s) in school	Block (5) Multipurpose Hall	Block (6) Art Book A.T. Lab	Block (7) Hostel Sutlej House	Block (8) Hostel Ravi House
No. of Floors in the Block	One	One	Two	Two


Details of Blocks(s) in school	Block (9) Gymnasium	Block (10) Mess	Block (11) Swimming Pool	Block (12) Auditorium
No. of Floors in the Block	One	One	Two	Two


The building is owned by Sri Dashmesh Academy, Anandpur Sahib have complied with the Building Safety requirements in accordance with National Building Code Rules and verified by the officers concerned of Public Work Department, B&R, Anandpur Sahib on 26<sup>th</sup> February, 2024 in the presence of Maj Gen J S Ghumman, VSM (Retd), Secretary of the Trust and Col.Rama Kant Pandey (Retd.), Principal of the institution and that the building/premises is fit for occupancy for running school w.e.f. 26<sup>th</sup> February, 2024 to 31<sup>st</sup> March, 2025 for a period of One years in accordance with rule and subject to compliance of the specific conditions as appended :-

- 1) Maintenance of school building will be carried out by you every year.
- 2) Building terrace and surrounding must be free from Rainy/waste water.
- 3) If any cracks appear in the building, then it must be repaired as soon as possible.
- 4) Safety of Building is solely your responsibility and all fire fighting material must be in good/useable conditions.
- 5) The internal structural stability of this school building cannot be checked from the external appearance. Therefore, if at any time there is damage due to deficiency in the structural design of the building, then the school authority itself will be responsible for it.
- 6) In case of flood damage to the building and any settlement in walls/foundations and sagging in roofs, the school authority will immediately bring to the notice of this department.

Issued on 26<sup>th</sup> February, 2024 at Anandpur Sahib by PWD B&R Department.

  
**Chairman**  
School Management Committee  
Sri Dasmesh Academy  
Sri Anandpur Sahib-140116  
Distt. Rupnagar (Pb)

  
Sub Divisional Engineer,  
Const. Sub Divn.PWD B&R Br.,  
Sri Anandpur Sahib.

  
**Principal**  
Sri Dasmesh Academy  
Sri Anandpur Sahib-140116  
Distt. Rupnagar (Pb.)